

CSIR – Central Scientific Instruments Organisation

No. CSIO/2023-24/418

Date: 5th October, 2023

Sub: Repair, servicing and replacement of faulty input breaker box of UPS


The following works related repair, servicing and replacement of faulty input breaker box of UPS are required to be carried out onsite in CSIO Chandigarh APC make UPS (15 kVA) connected to equipment:

- Repair and Servicing of 15 kVA UPS (Qty: 1 No.)
- Replacement of UPS input Breaker Box
- Wire-16 sq mm for UPS connection – 5 mtr
- Wire UV8 for UPS connection – 6 mtr

Interested firms, who can undertake the above work, can send their quotations through e-mail to the undersigned (mukeshk@csio.res.in) on or before 09.10.2023, 1 PM.

Other Terms & Conditions:

1. Delivery: F.O.R. CSIO Chandigarh
2. Payment Terms: Within 30 days after delivery and installation



(Dr. Mukesh Kumar)
Pr. Scientist, Thin Film Coating Lab
Ph – 0172 2672487
E-mail: mukeshk@csio.res.in